

QAPP Review for the PA Watershed Planning Meeting

May 27, 2025

For training purposes only

This presentation is not intended and should not be interpreted as, representing the position or policy of EPA on matters discussed.

EPA Region 3 Review Process

- Your organization's Quality Assurance Manager (QAM)
- EPA's Delegated Approving Officials (DAO) and Designated Project Manager
- 45 days for a new review; 15 days for a revision
- Process and responsibilities are described in the Region 3 QMP
- Typically, review is to assure the required elements in the EPA Quality Directives are present and complete

Quality Assurance Review References

QA Procedures / Directives

- Environmental Information Quality Policy, March 20, 2024
- Quality Management Plan Standard, March 20, 2024
- Quality Assurance Project Plan Standard, April 3, 2024

QA Guidance Documents

- Guidance on Systematic Planning using the Data Quality Objectives Process (QA/G-4)
- Guidance for Quality Assurance Project Plans (QA/G-5) [to be updated]
- Guidance on Choosing a Sampling Design for Environmental Data Collection (QA/G-5S)
- Guidance for Preparing Standard Operating Procedures (QA/G-6)
- + others see the <u>EPA Quality website</u>

Required Elements for QAPPs

- GROUP A Project Management and Information/Data
 Quality Objectives 12 Elements
- GROUP B Implementing Environmental Information
 Operations 7 Elements
- GROUP C Assessment and Oversight 2 Elements
- GROUP D Environmental Information Review and Usability Determination – 2 Elements

Graded Approach

- Organizations and programs vary according to the specific objectives and needs.
- The level of detail in quality documents (e.g., QAPP) depends on program or project scope, purpose, and intended use of the data.



The graded approach does not eliminate the requirement of QMPs and QAPPS and other quality documents.



If a QAPP element does not apply to your project, then state this and explain why in that section.

A1 – Title Page	Missing Title Page entirely or
	Missing grant or cooperative agreement number
	or missing or missing contract number and task
	order number.
A2 – Approval Page	Missing Approval page or
	Missing Operations Manager or designee for the
	project or Project QAM or individual with QAM
	responsibilities for the project or EPA signature
	from operations (COR or PO) and EPA QAM or
	designee.
A3 – Table of Contents, Document Format, and	Missing Table of Contents or
Document Control	
	Mismatch between page numbers in document
	and table of contents or
	Document control missing or incomplete

A4 – Project Purpose, Problem Definition, and	Missing systematic planning or
Background	
	Weak connection between planning and proposed
	project or
	Missing type, quantity, and quality of information
	needed for its intended use and description of the
	acceptance and performance criteria.
	acceptance and performance criteria.
	Missing Identification of the applicable regulatory
	programs and standards; conceptual site model(s);
	a discussion that directly links the results of the
	environmental information operations to possible
	actions.
	Missing background information or background
	information incomplete or not up to date
A5 – Project Task Description	Missing task description or
	Schedule not up to date
A6 – Information/Data Quality Objectives and	Missing Data Quality Objectives or missing
Performance/Acceptance Criteria	performance/acceptance criteria
A7 – Distribution List	Missing distribution list or missing personnel on list
	such as subcontractors.

A8 – Project Organization	 Missing one or more key personnel such as: Senior manager having executive leadership authority for the organization The Project QAM for the organization conducting the environmental operations.
A9 - Manager Independence – Project Quality Assurance	QAM role is missing or cannot be readily identified or QAM is not independent of environmental information operations
A10 – Project Organization Chart and Communications	Missing project organizational chart or one or more required elements in the chart are missing such as QAM independence from environmental information operations.
A11 – Personnel Training/Certification	Missing or incomplete
A12 – Documents and Records	Incomplete or lacking description of documents that will be produced or disposition of documents.

B1 – Identification of Project Environmental Information Operations	Refer to guidance. Environmental Information Operations are an expansion of what is being collected (formerly data). Refer to Chapter 2 of Guidance for Choosing a Sampling Design for Environmental Data Collection (QA/G-5s) (EPA, 2002a).
B2 – Methods for Environmental Information Acquisition	Incorrect or out of date methods or missing SOPs or holding times exceeded. Refer to method references such as Clean Water Act Analytical Methods or Guidance for Preparing Standard Operating Procedures, EPA QA/G-6 from March 2001 or Guidance on Quality Assurance for Environmental Technology Design, Construction, and Operation
B3 – Integrity of Environmental Information	Missing procedures for sample handling or missing laboratory information.
B4 – Quality Control	Missing or incomplete quality controls for environmental information operations.

B5 – Instrument/Equipment Calibration, Testing, Inspection, and Maintenance	Missing instrument calibration, inspection or maintenance information
B6 – Inspection/Acceptance of Supplies and Services	Missing or incomplete
B7 – Environmental Information	Needs to describe the environmental
Management	information management process.

C1 – Assessments and Response Actions	Describe what will be assessed and response actions.
C2 – Oversight and Reports to	Reports to management not included.
Management	

D1 – Environmental Information Review	Needs to include procedures for verification and validation
D2 – Useability Determination	Needs to describe or reference procedure to ensure environmental data is useable. Often involves PARCS.



QA contact: Elizabeth Gaige

gaige.elizabeth@epa.gov

NPS program contact: Angela Padeletti

Padeletti.Angela@epa.gov